Appin No. 10/728,971 Amet. Dated October 14, 2004 Response to Office action of September 17, 2004

2

### Amendments to the Specification:

### The paragraph beginning at Page 1, line 1, to be amended as follows:

This is a Continuation Application of USSN09/835,702 filed on April 16, 2001 now U.S. Patent No. 6.742.873.

### The Abstract beginning at Page 70 is to be amended as follows:

A printhead includes an elongate substrate that defines three groups of ink supply channels, each group being in fluid communication with a respective ink of a predetermined color and extending along a length of the substrate along three substantially parallel paths. A plurality of nozzle arrangements is positioned on the substrate. Each nozzle arrangement includes a nozzle chamber structure that is positioned on the substrate to define a nozzle chamber in fluid communication with an ink supply channel and an ink ejection port in fluid communication with the nozzle chamber. A micro-electromechanical ink ejection mechanism is positioned on the substrate operatively with respect to the nozzle chamber to eject ink from the ink ejection port.

Figure 85

BEST AVAILABLE COPY

# This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
COLOR OR BLACK AND WHITE PHOTOGRAPHS
GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
□ other.

### IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.